

### Surface Affected Area

Permit ID: B-1156

National ID: Null

Permittee: ST JOSEPH COAL CO

Law: B

Reclamation Status: Disturbed

Surface Mining Method: Null

Release Eligibility: Null

Calculated Area: 26.066552

Reported Area: 26

Re-Mined Area: Null

Permit Application Date: 7/14/1976

Application Approval Date: Null

Re-Permit: Null

Source Documents: B-1156.TIF

### Coal Mining - Surface Mine - Inactive Released

Permittee: ST JOSEPH COAL CO

Operation Status: Abandoned

Mine Name: Null

Permit ID: B-1156

MSHA ID: Null

State Mine ID: Null

National ID: OH-B-1156

CoalBed1: Null

CoalBed2: Null

CoalBed3: Null

Date of Map: Null

Inspectable Unit Status: Null

Surface Mining Method: Null

Post-SMCRA: No

Calculated Area: 18.648962

Reported Area: 18.4

Re-Mined Area: Null

Permit Application Number: Null

Permit Application Type: Null

Permit Application Date: 7/14/1976

Permit Application Approval Date: Null

Source Documents: B-1156.TIF

### Historic Coal Surface Mine

Site ID: 7805

Rec\_code: Null

Pub\_Year: 1961

Alt\_Year: 0

COUNTY: Tuscarawas

Source: AMLIS

Visited: Yes

Date\_Visited: 9/16/2015 12:11:16 PM

AMLIS\_Eligible: No

Information was obtained from the Ohio Department of Natural Resources, Mines of Ohio. For more details please visit <https://gis.ohiodnr.gov/MapView/?config=OhioMines>